

BLUED &
STAINLESSCALIBER
9mm

RUGER®

P85® & P85® MKII

Autoloading Pistols



All parts orders for the P85 and P85 MKII Model pistols should be sent to: Sturm, Ruger & Co., Inc., Parts Department, 200 Ruger Road, Prescott, AZ 86301, 520-778-6555. Payment in the form of a check or money order must accompany your order. We cannot comply with open account, credit cards or C.O.D. requests. Minimum parts order is \$1.00 plus \$3.50 shipping and handling charge. Order parts by part name and part number and include the entire serial number of the firearm for which the parts are being ordered. The price shown for parts does not include the minimum net labor charge of \$15.00 plus \$5.00 shipping and handling if parts are factory fitted. All factory fitted parts are fitted on an exchange basis only. We will not return the replaced parts. Work performed will bear a net minimum labor charge of \$15.00 plus a \$5.00 shipping and handling charge. The charge for metal refinishing (except for the aluminum frame, which we cannot refinish) is \$35.00 plus a \$5.00 shipping and handling charge.

Because it is a serial-numbered component, the frame is defined as a "firearm" by Federal Law and is not sold as a separate component.

If no price appears in the "Stainless" column, the part is available in blued steel only and is used on all models. Likewise, if no price appears in the "Blued" column, the part is available in stainless steel only and is used on all models. A few components (for example, grip panels) are the same for blued and stainless models.

SAFETY WARNING: IMPORTANT SAFETY WARNING TO OWNERS OF RUGER P85 PISTOLS MADE BETWEEN 1987-1990: If the firing pin is broken, these pistols may fire when the safety or decock lever is depressed. Please contact us at Sturm, Ruger and Company, Dept. S, Ruger Road, Prescott, AZ 86301 (phone: 1-800-424-1886), and we will schedule your pistol for a FREE factory safety modification to prevent such firing. This offer does not apply to P85 Mark II pistols, pistols with an "R" on the manual safety, or any other P-Series pistol. These firing pins are very durable and breakage has occurred only in a handful of cases. In the interest of complete safety, users should always point the pistol in a safe direction when decocking. However, the new design components eliminate the possibility of this kind of accidental discharge.



WARNING—PARTS PURCHASERS



It is the purchaser's responsibility to be absolutely certain that any parts ordered from the factory are correctly fitted and installed. Firearms are complicated mechanisms and IMPROPER FITTING OF PARTS MAY RESULT IN A DANGEROUS MALFUNCTIONING, DAMAGE TO THE FIREARM AND INJURY TO THE SHOOTER AND OTHER PERSONS. The purchaser and installer of parts must accept full responsibility for the correct adjustment and functioning of the firearm after such installation.

PARTS MUST FIT CORRECTLY

Design, specifications and prices are subject to change without notice. The Sturm, Ruger & Company "LOGO", "RUGER" and "P85" are registered U.S. trademarks.

STURM, RUGER & Company, Inc.
Southport, Connecticut 06490 U.S.A.

P85® & P85® MKII

COMPONENT PARTS AND SUGGESTED RETAIL PRICES ORDER THESE PARTS FROM PRESCOTT PLANT

Part Name	Part No.	Model	Caliber 9mm	Blued	Stainless
* Barrel, Assembly	KV00612-100	P85, P85 MKII	•	—	\$74.00
Barrel Link	V00700	P85, P85 MKII	•	\$.75	—
Barrel Link Pin	KV00350	P85, P85 MKII	•	—	.50
* Blocker Lever	KV02100	P85, P85 MKII	•	—	6.75
Blocker Lever Spring	V01900	P85	•	1.00	—
Blocker Lever Spring	KV01950	P85 MKII	•	—	1.00
A Case Combo, 9mm, Not Illustrated, Specify Serial Number	PGCC-9mm	P85, P85 MKII	•	42.30	42.30
A Case Only, Centerfire, Not Illustrated	PGC-CF	P85, P85 MKII	•	15.00	15.00
Ejector	V00900	P85, P85 MKII	•	5.00	—
Ejector Pin	V01200	P85	•	.50	—
Ejector Pin	KV01250	P85 MKII	•	—	.50
Ejector Spring	KV00951	P85, P85 MKII	•	—	3.00
* Extractor	V01400	P85, P85 MKII	•	8.50	10.00
Firing Pin	Serial Number Required	P85	•	—	12.75
Firing Pin	KV01118	P85 MKII	•	—	12.75
* Firing Pin Block	KV02101	P85, P85 MKII	•	—	5.00
Firing Pin Block Spring	KQ05600	P85, P85 MKII	•	—	.50
Firing Pin Plunger, Not Illustrated	KH05100	P85, P85 MKII	•	—	1.50
Firing Pin Spring	V01800	P85	•	.50	—
Firing Pin Spring	KV01850	P85 MKII	•	—	.50
Frame	V00200	P85	•	Not Offered For Sale	
Frame	V00201	P85 MKII	•	Not Offered For Sale	
Front Sight, Must Be Drilled For Cross Pin	V03203	P85, P85 MKII	•	2.50	—
Front Sight Cross Pin, 2 Req'd.	V04700	P85, P85 MKII	•	ea. .50	—
Grip Panel Screw, 2 Req'd.	V01300	P85, P85 MKII	•	ea. .50	—
Grip Panels, Sold in Pairs Only	V00800	P85, P85 MKII	•	6.00	—
Guide Rod	V22000	P85, P85 MKII	•	3.00	—
Guide Rod/Recoil Spring Assembly	V22000-100	P85, P85 MKII	•	3.50	—
* Hammer	KV04003	P85, P85 MKII	•	—	17.75
* Hammer, Assembly	KV04003-100	P85, P85 MKII	•	—	18.25
Hammer Pivot, Assembly	V22300	P85, P85 MKII	•	1.50	1.75
Hammer Spring	V00400	P85, P85 MKII	•	.50	—
Hammer Spring Seat, Without Lanyard Loop, Not Illustrated	V02400	P85, P85 MKII	•	3.25	—
Hammer Spring Seat, With Lanyard Loop	V02402	P85, P85 MKII	•	3.25	—
Hammer Spring Seat Pin	KV02550	P85, P85 MKII	•	—	.50
Hammer Strut	V01600	P85	•	1.25	—
Hammer Strut	V01601	P85 MKII	•	1.25	—
Hammer Strut Pin	V05100	P85	•	.50	—
Hammer Strut Pin	KV05150	P85 MKII	•	—	.50
Lock & Keys	PGLK	P85, P85 MKII	•	2.50	2.50
A Magazine Complete, 10-Shot Capacity	P-15/10	P85, P85 MKII	•	21.00	—

SAFETY WARNING: IMPORTANT SAFETY WARNING TO OWNERS OF RUGER P85 PISTOLS MADE BETWEEN 1987-1990: If the firing pin is broken, these pistols may fire when the safety or decock lever is depressed. Please contact us at Sturm, Ruger and Company, Dept. S, Ruger Road, Prescott, AZ 86301 (phone: 1-800-424-1886), and we will schedule your pistol for a FREE factory safety modification to prevent such firing. This offer does not apply to P85 Mark II pistols, pistols with an "R" on the manual safety, or any other P-Series pistol. These firing pins are very durable and breakage has occurred only in a handful of cases. In the interest of complete safety, users should always point the pistol in a safe direction when decocking. However, the new design components eliminate the possibility of this kind of accidental discharge.

*Parts designated by an asterisk must be factory fitted. These parts are fitted on an exchange basis only. We will not return the replaced parts. We will not return any part that is broken, malfunctioning, badly worn or has been modified. See "Warning — Parts Purchasers" front cover.

A Ruger Accessories should be ordered through a Ruger Distributor. Refer to booklet B1 for a list of Distributors. Refer to booklet B2 for a list of Parts Source. For a complete list of Ruger Accessories refer to booklet A1.

P85® & P85® MKII

COMPONENT PARTS AND SUGGESTED RETAIL PRICES ORDER THESE PARTS FROM PRESCOTT PLANT

Part Name	Part No.	Model	Caliber 9mm	Blued	Stainless
Magazine Floor Plate, Pinned, 10-Shot	V01007	P85, P85 MKII	•	\$ 1.25	—
Magazine Floor Plate, Snap On, 10-Shot	V01009	P85, P85 MKII	•	1.25	—
Magazine Floor Plate, Metal, 15-Shot	V01000	P85, P85 MKII	•	1.25	—
Magazine Floor Plate, Plastic, 15-Shot	V01003	P85, P85 MKII	•	1.25	—
Magazine Follower	V02907	P85, P85 MKII	•	1.50	—
Magazine Latch, Left	V02601	P85, P85 MKII	•	5.25	—
Magazine Latch, Right	V02600	P85, P85 MKII	•	5.25	—
Magazine Latch Spring	V02700	P85, P85 MKII	•	.75	—
A Magazine Loader	PML	P85, P85 MKII	•	5.00	—
Magazine Shell, 10-Shot, Pinned	V00504	P85, P85 MKII	•	16.75	—
Magazine Shell, 10-Shot, Snap On	V00506	P85, P85 MKII	•	16.75	—
Magazine Spring, 10-Shot	V03003	P85, P85 MKII	•	1.75	—
Magazine Spring, 15-Shot	V03000	P85, P85 MKII	•	1.75	—
Magazine Spring Seat	V03100	P85, P85 MKII	•	.75	—
Rear Sight	V03301	P85, P85 MKII	•	6.00	—
Rear Sight Lock	V07900	P85 MKII	•	3.00	—
Rear Sight Lock Screw	V08001	P85, P85 MKII	•	1.00	—
Recoil Spring	V02800	P85, P85 MKII	•	.50	—
Safety Detent Ball	KV06020	P85 MKII	•	—	\$.50
Safety Detent Plunger	V04600	P85, P85 MKII	•	.50	1.50
Safety Detent Plunger Spring	KV04100	P85, P85 MKII	•	—	.50
Safety, Left	Serial Number Required	P85	•	15.00	15.50
Safety, Left	V01500	P85 MKII	•	15.00	15.50
Safety, Right	Serial Number Required	P85	•	12.50	16.75
Safety, Right	V01580	P85 MKII	•	12.50	16.75
* Sear	KV02217	P85, P85 MKII	•	—	9.50
Sear Pivot Bearing	KV05750	P85, P85 MKII	•	—	.75
Sear Pivot Pin	KV04450	P85, P85 MKII	•	—	.50
Sear Spring	V04300	P85	•	1.00	—
Sear Spring	KV04350	P85 MKII	•	—	1.00
* Slide	V00100	P85	•	101.25	110.00
* Slide	V00102	P85 MKII	•	101.25	110.00
Slide Stop	V03700	P85, P85 MKII	•	13.00	14.50
Slide Stop Spring	V04500	P85, P85 MKII	•	.50	—
Slide Stop Spring Retainer	V03400	P85, P85 MKII	•	.50	.50
Trigger	KV03900	P85, P85 MKII	•	—	8.50
* Trigger Bar	KV01700	P85, P85 MKII	•	—	28.50
Trigger Bar Plunger	V03500	P85, P85 MKII	•	.50	.50
Trigger Bar Plunger Spring	V03600	P85	•	.50	.50
Trigger Bar Plunger Spring	KV03650	P85 MKII	•	—	.50
Trigger Bar Spring Retainer	V04200	P85, P85 MKII	•	.50	.50

SAFETY WARNING: IMPORTANT SAFETY WARNING TO OWNERS OF RUGER P85 PISTOLS MADE BETWEEN 1987-1990: If the firing pin is broken, these pistols may fire when the safety or decock lever is depressed. Please contact us at Sturm, Ruger and Company, Dept. S, Ruger Road, Prescott, AZ 86301 (phone: 1-800-424-1886), and we will schedule your pistol for a FREE factory safety modification to prevent such firing. This offer does not apply to P85 Mark II pistols, pistols with an "R" on the manual safety, or any other P-Series pistol. These firing pins are very durable and breakage has occurred only in a handful of cases. In the interest of complete safety, users should always point the pistol in a safe direction when decocking. However, the new design components eliminate the possibility of this kind of accidental discharge.

*Parts designated by an asterisk must be factory fitted. These parts are fitted on an exchange basis only. We will not return the replaced parts. We will not return any part that is broken, malfunctioning, badly worn or has been modified. See "Warning — Parts Purchasers" front cover.

A Ruger Accessories should be ordered through a Ruger Distributor. Refer to booklet B1 for a list of Distributors. Refer to booklet B2 for a list of Parts Source. For a complete list of Ruger Accessories refer to booklet A1.

P85[®] & P85[®] MKII

